EXHIBIT C

Case: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 Page 1 of 56



Toll Free: (800) 435-7764
Email: myclaim@farmersinsurance.com
National Document Center
P.O. Box 268992
Oklahoma City, OK 73126-8992
Fax: (877) 217-1389

11/06/2018

Pacific Gas And Electric Attn: PG&E Law - Claims Dept. 1850 Gateway Blvd. 6th Floor Concord. CA 94520

Our Insured: Ghannam, Ron

Our Claim #: 099 SUB 3011311133-1

Date of Loss: 08/02/2018

Your Insured: PG&E Law - Claims Dept.

Your Claim #:

Amount Owed: \$716.78

Dear PG&E Law - Claims Dept.:

Our investigation has established that the above loss was caused by the negligence of your insured.

We have made payment to our insured for the damage. By virtue of our subrogation rights this letter is to advise you that we are seeking reimbursement from you for the amount of damages. Our insured incurred damages to their property located at 1814 Broadway St., Vallejo, CA 94589 due faulty workmanship by your contractors. Water overflowed from toilets and backed up into their business. A plumber (report attached) snaked the line and found rock and dirt in the sewer lateral near the area PG&E had been working. The damage was due to the sewer pipe being crushed by PG&E. Please find attached our supporting documents. Please note, our insured has out of pocket expenses.

Be aware that no partial payment to Mid-Century Insurance Company that is less than the full amount claimed herein will be considered in any way an acceptance of benefits, a novation or an accord and satisfaction of this claim without the express written release of our claim executed by an individual who is a member of our subrogation department. Therefore, our legal rights to enforce collection on the remaining amount of the claim shall not be waived or estopped due to a partial payment by you or someone acting on your behalf.

It is our desire to settle this claim without causing you the additional time and cost of litigation or arbitration. After reviewing the enclosed, please call me 512-533-8862 to discuss resolving this matter. If additional support for our claim is required, please let me know so the requested information can be sent to you.

Please send payment to:

National Document Center

FYVWB8VS PO Box 268992 se: 19-30088

8 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 PexeraBIT C

of 56

Oklahoma City, Ok 73126

Sincerely,

Craig Remeny

Business Insurance Claims Representative

Mid-Century Insurance Company

512-533-8862

craig.remeny@farmersinsurance.com

FYVWB8VSase: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 PEXHIBIT C

of 56

HEART Claim Pics

PDF created on August 10, 2018 at 9:32:56 PM PDT

Claim Unit Number: 3011311133-1-1

Notes:


Loss discovery photos


Case: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 Peger4BIT C












































































HEART Claim Pics

PDF created on August 10, 2018 at 7:22:22 PM PDT

Claim Unit Number: 3011311133-1-1

Notes:

Inspection photos

Case: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 Page BIT C



Risk shot



Right elevation



Area recently worked on by pge per insured








Ov of floor/carpet at entry



Entrance into garage from entry



Entrance into business



Fans placed for drying



Inventory on floor




Display raised





Ov towards Office



Ov towards bathroom 1



Base detached



Ov entrance into bathroom





Floor wet at time of my inspection








Staining indicative of pooled water





Overview towards office




Baseboards have been detached




Mildew odor at the time of my inspection



Wet shelving in carpet in office strong mildew odor





Office shares a wall with bathroom one and bathroom two



Rubber cove base detached from wall



Overview towards storage area




Water staining noted on wall



Overview of storage room



Water staining noted at shelving and panel



Continued overview of storage area



Water staining noted on drywall



Continued overview



No water staining noted



Ov bathroom two, at rear of building, Shares wall with bathroom one





No evidence of pooled water in bathroom. Employee who came in the morning I've lost discovery noted water coming from the toilet



No evidence of damage



No evidence of damage




No evidence of damage



No dmg








Overview towards garage/installation shop



Overview of employee entrance door from which loss was discovered, water was streaming out




Garage shared wall with storage room



Damaged inventory







Staining along wall noted














Overview of employee entrance door from which loss was discovered, water was streaming out

Angel Miranda II

All Plumbing

1933 Georgia Street Vallejo , CA 94590 Business Phone/Fax: (707)649-2427

Cell: (707)332-1939 LC# 439170

1C# 439170

Invoice

Date Invoice # 7/27/28/10 8063

BROADWAY ANTO SOUND

(814 BROADWAY

VALLEDO CA.

945-90

Qty

Description

P.O. No. Terms

1814 Brandam Ample han

Rate Amount

Removal of the form bout bother comp

3" N/Enr-out, 3/ 10 to fines / sing

to Report 65 in Front of building

to Report 65 in Front of building

45 to 70' Line 15th is beoleen

45 to 16th in the 15 to 1/6th.

46 to 1/6th.

47 to 1/6th.

48 to 1/6th.

\$15000

Case: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 FRAMBIT C


Total

Bullseye Leak Detection, Inc.,4015 Seaport Blvd., West Sacramento, CA, 95691; office@bullseyeleak.com; 916-760-8944



1814 Broadway St, Vallejo, Ca

Inspection on 2018-08-15 1814 Broadway St, Vallejo, Ca



Area: None Action: None Comments: Ref #: 22552

Taken on: 2018-08-15 15:50:50

Taken at: 38.13226029,

-122.25218471

Full resolution image





Area: None
Action: None
Comments:
Ref #: 22552

Taken on: 2018-08-15 15:58:24

Taken at: <u>38.1323119</u>,

-122.25204674

Full resolution image

Area: None Action: None Comments: Ref #: 22552

Taken on: 2018-08-15 16:07:11

Taken at: 38.1323688, -122.2521024

Full resolution image







Area: None Action: None Comments: Ref #: 22552

Taken on: 2018-08-15 16:07:17 **Taken at:** 38.132329, -122.2520551

Full resolution image

Area: None Action: None Comments: Ref #: 22552

Taken on: 2018-08-15 16:43:36

Taken at: 38.13232161,

-122.25215247

Full resolution image

Report generated by zInspector.com

Entered: 03/22/21 14:42:57 EXTEST C



4015 Seaport Blvd West Sacramento Ca 95691 Lic. # 935197

Bill To

Farmers Insurance Exchange PO Box 268994 Oklahoma City, OK 73126-8994

Invoice

Date	Invoice #	Terms	Due Date	
8/15/2018	22552d	2/10 Net 30	9/14/2018	

Phone Number Fax Number

916-760-8944 916-760-8970

E-mail

office@bullseyeleak.com

Web Site

www.bullseyeleak.com

P.O. No.	Technician
	Dan

			Dan
Description	Qty	Rate	Amount
Claim# 3011311133-1			
1814 Broadway St			
/allejo, CA 94589			
Jpon arrival I met with the homeowner.			
Area of concern: I was told sewage surfaced soon after PG&E had performed work out front of the business.			
The owner had hired a plumber who could not clear the line.			
First point of camera entry: Clean-out First camera run: There was no visibility during the inspection as the line was. It was			
illed with standing sewage. I ran the camera approximately 60 ft when I found an			
obstruction I could not pass. I located the obstruction at the edge of the PG&E trench. It appears that the sewer line has been crushed by trade damage. The sewer line is			
approximately 4' deep and the gas trench was likely at a higher elevation so they did			
not know there was a conflict during their work. Anomaly found: Yes			
Anomaly location: at PG&E trench on Broadway side of the building.			
Approximate anomaly depth: 4 feet Demarcation of anomaly: Paint			
Note: Due to poor visibility and/or limitations of the inspection equipment, we cannot			
determine pipe material with 100% accuracy and do not guarantee our findings with regard to pipe material.			
nsurance commercial leak detection		400.00	400.00
extra hour		175.00	175.00

If Bullseye Leak Detection, Inc. is required to return for an additional inspection or leak detection, it will be considered above and beyond the scope of this invoice and will be billed at the current prevailing rate. All markings are good for 30 days and only on utilities marked by Bullseye Leak Detection, Inc. Payment is due upon completion of work unless otherwise agreed to in writing and authorized by an officer of Bullseye Leak Detection, Inc.

Ihank	you	tor	your	business.
-------	-----	-----	------	-----------

Total	\$575.00
Payments/Credits	\$0.00
Balance Due	\$575.00

Case: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 Page IBIT C



Toll Free: (800) 435-7764

Email: myclaim@farmersinsurance.com

National Document Center

P.O. Box 268994

Oklahoma City, OK 73126-8994

Fax: (877) 217-1389

Payment Log

Account Number: HHH263224
Date of Loss: 08/02/2018

Insured's Name: BUSINESS GHANNAM, RON Claim Number: 3011311133-1-4, 3011311133-1

Payment Type	Date issued	Payee	Check Number	Payment Amount
BPP	08/23/2018	AND PREMIER AUTO	1621356132	\$150.00
		SOUND		
Building	08/28/2018	SERVPRO INDUSTRIES	1621387555-0003	\$566.78
		INC		
Payment Total:				\$716.78

Case: 19-30088 Doc# 10441-3 Filed: 03/22/21 Entered: 03/22/21 14:42:57 Page 55.01-55 Entered: 03/22/21 14:42:57